

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2659	DATE	November 25 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the heavy-duty trucks equipped with mechanical automatic transmission, it has been found that the wiring rubbed against the wheel park bracket due to inadequate installation position of the floor wiring clip inside the cab. Thus, if it is used as is, the wiring may be short-circuited, thereby making it impossible to shift gears in the worst case.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-CXY77S8J	GIGA	2007	1
PDG-CYH52W8		2007	1
PKG-CYH77W8		2007	1
PJ-CYJ51W6		2005	1
PDG-CYJ52W8A		2007	1
PJ-CYJ77W6		2007	2
PKG-CYJ77W8 PKG-CYJ77W8A		2007	98
KL-CYL51V4		2004	1
PDG-CYL52V8 PDG-CYL52V8A		2007	2
PDG-CYL77V8 PKG-CYL77V8 PKG-CYL77V8A		2007	70
PKG-CYM77Q8		2007	6
PKG-CYM77V8		2007	4
PDG-CYY52V8		2007	2
PKG-CYY77V8		2007	1
PKG-CYY77V8J		2007	2
PDG-CYZ52V8		2007	2
PKG-CYZ77V8		2007	1
PJ-EXD52D6		2007	30
PKG-EXD52D8		2007	38

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-EXD52E8	GIGA	2007	18
PKG-EXY52J8		2007	18
PDG-EXZ52J8		2007	10
PKG-EXZ52J8			
		TOTAL	310