

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2653	DATE	Nov.17.2010
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to improper electrical contact position in the intermittent operation relay installed to the windshield wiper switch, if the frequency of use for the intermittent operation is high, the contact may wear and separate, causing the short circuit. As a result, the windshield wiper could become inoperative and, in the worst case, the relay may emit smoke and burn out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-BB58	TOYOTA COASTER	1999-2004	91
KK-HDB50		1999-2004	1,357
KK-HDB51		1999-2004	1,617
KK-HZB40		1999-2004	2,670
KK-HZB41		1999-2004	232
KK-HZB50		1999-2004	2,436
KK-HZB46V	TOYOTA COASTER BIG VAN	1999-2004	197
KK-HZB56V		1999-2004	114

KK-BB58M	HINO Liesse II	1999-2004	58
KK-HDB50M		1999-2004	572
KK-HDB51M		2001-2004	192
		2001	1
KK-HZB40M		2001-2004	336
KK-HZB50M		1999-2004	1,118
		TOTAL	10,991