

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1720	DATE	December 2. 2010
MANUFACTURER	Sundiro Honda Motorcycle Co., Ltd.		
DESCRIPTION OF DEFECT	Regarding the parts to hold turn signal switch operating knob in place, it has been found that dissimilar materials are used for them and certain parts may be corroded by rainwater and the like entered the switch, and intended operation of the turn signal switch can be thereby precluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AF67	TODAY	2007～2008	35,300
		2007～2009	65,839
		TOTAL	101,139