

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2670	DATE	December 7 ,2010
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>On certain heavy duty sight seeing buses,</p> <p>1) due to improper installation position of the resistor for the air conditioner component, the resistor may come into contact with the resistor cover and the short-circuit from the electrified resistor to the resistor cover can be caused, which may result in an ignition.</p> <p>2) due to improper combination of the pipes of the combustion heater unit for cabin heating and the clamps that connect the pipes and the hoses which supply the coolant to and receive the coolant from the heater, the pipes and the hoses can be disconnected and the leakage of a large quantity of the coolant can be caused, which may result in the vehicle inoperative.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-RU1ESBJ	ISUZU GALA	2010	12
LDG-RU8JHBJ		2010	7
SDG-RU8JHBJ			
		TOTAL	19