

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 6 6 5	DATE	D e c . 0 7 . 2 0 1 0
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the rear direction indicators, some cracks may develop at the screw tightening section of the lens due to the components in the plastic-made washer of the screw to fasten the lens. Because of this reason, the continuous use of the direction indicators may have the cracks progress more and the worst-case scenario, the lens mentioned here may come off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-SA36J	JOG CE50	2010	23,520
JBH-SA39J	JOG CE50D	2010	1,960
	JOG CE50ZR	2009~2010	5,544
		TOTAL	31,024