

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2668	DATE	December 9 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the installation area of the oil pipe for lubricating the vacuum pump, it has been found that the bolts to secure the pipe would be loosened due to a lack of axial force. Thus, if they are used as are, oil may leak from the packing, and in the worst case, the engine may be subjected to seizure.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PB-NKR81A PB-NKR81AD PB-NKR81AN PB-NKR81AR PB-NKR81N PB-NKR81R VD-NKR81AN	ELF	2006-2007	2,675	
AFG-NKR82AN AFG-NKR82N		2006-2007	58	
PB-NKS81A PB-NKS81AN PB-NKS81AR PB-NKS81N		2006-2007	197	
PA-NPR81DR PA-NPR81N PA-NPR81R PB-NPR81AN PB-NPR81AR VD-NPR81AN		2006-2007	697	
AFG-NPR82AN AFG-NPR82N		2006-2007	74	
PB-NPS81AN PB-NPS81AR PB-NPS81N		2006-2007	29	
PB-AKR81A PB-AKR81AD PB-AKR81AN PB-AKR81AR PB-AKR81N PB-AKR81R		ATLAS	2006-2007	184
AFG-AKR82AN			2006	1
PB-AKS81AN PB-AKS81AR			2006-2007	10
PA-APR81N PA-APR81R PB-APR81AN PB-APR81AR			2006-2007	81
PB-APS81AN PB-APS81AR	2006		2	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-BKR81A PB-BKR81AD PB-BKR81AN PB-BKR81AR PB-BKR81N PB-BKR81R	CONDOR	2006-2007	17
AFG-BKR82AN AFG-BKR82N		2006-2007	2
PB-BKS81AN		2007	1
PA-BPR81N PA-BPR81R PB-BPR81AN		2006-2007	11
AFG-BPR82AN		2006	1
PB-LKR81A PB-LKR81AD PB-LKR81AN PB-LKR81AR PB-LKR81N PB-LKR81R		TITAN	2006-2007
PB-LKS81A PB-LKS81AN PB-LKS81AR	2006-2007		16
PA-LPR81DR PA-LPR81N PA-LPR81R PB-LPR81AN PB-LPR81AR	2006-2007		84
			TOTAL