

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2671	DATE	Dec.9.2010
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Speed sensor harness has a possibility to become contact with rear tire due to incorrect harness routing instruction. In consequence, the harness is disconnected and may lead to speedometer malfunction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-CF4MA	ADDRESS V125	2010	9,092
		TOTAL	9,092