

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2666	DATE	December 10. 2010
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	In the steering system, a fingernail of the side clutch fork used inside the transmission might not be heat-treated. Therefore, when it continues to use, the fingernail of the side clutch fork might be worn out and it cause un-operated clutch conditions. In the worst case, there is a possibility that the steer operation might become difficult to condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	MR750A	2010	1
TOTAL			1