## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2674	DATE	Dec. 10, 2010	
MANUFACTURE	TADANO LTD.			
DESCRIPTION OF DEFECT	As there were vehicles assembled without a retaining ring that acts to fasten the steering device's bearing and connection axle in the connection between the hydraulic steering pump and the steering shaft, in the worst case, there is the chance that a loss of steering could result from the this connection axle coming apart when the steering wheel's position is adjusted.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-T005	GR-120N-2	2010	21
JDS-T006	GR-160N-2	2010	14
JDS-T003	GR-250N-2	2010	59
JDS-T004	GR-600N-2	2010	3
EDR-EK04	RK120-3	2010	1
		TOTAL	98