VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2676	DATE	December 16 , 2010		
MANUFACTURER	Komatsu Ltd.				
DESCRIPTION OF DEFECT	Due to insufficient clearance between the rear defroster hose and the harness of brake lever position sensing switch on the machine for two-seat cab machine, the switch harness may be rubbed and damaged under machine vibration condition. Therefore if the machine is used continuously, in the worst case, the machine may not be able to travel.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
SB-W108	WA150-5	2006~2010		130
SC-W109	WA200-5	2006~2007		12
			TOTAL	142