

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2677	DATE	December 16 ,2010
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the CNG route buses, it has been found that electric wiring inside the engine compartment was short of heat resistance, so that heat from the exhaust pipe may cause damage to wiring cover. Thus, if they are used as are, the wiring may be disconnected, and in the worst case, the engine may be stalled and not restarted. Furthermore, the supporting mount for the catalyst and the exhaust silencer may be deteriorated, causing noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-LR233J1(kai)	ERGA MIO GALA MIO	1999-2002	19
KK-LR333J1(kai)		1999-2000	8
KC-LR233J(kai)	JOURNEY K	1998	1
KC-LR333J(kai)		1997-1999	11
		TOTAL	39