VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2682	DATE	20 th .Dec.2010	
MANUFACTURER	TCM CORPORATION			
DESCRIPTION OF DEFECT	Due to the welding of the mounting pipe for the control valve is inappropriate, a crack may occur in the pipe concerned by engine vibration. It might therefore reach oil leak from the crack point when continuing the vehicle operated.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS - F144	FD135 - 4 FD150S - 4 FD160S - 4	2008~2010	1 7
		TOTAL	1 7