

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 6 8 6	DATE	Dec.24.2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to inappropriate operations at the manufacturing process of the diode in power supply relay for engine control, an irregular contact can be made at a terminal in a relay. If the vehicle continues to be driven in this condition, the engine may not start or the engine may stall during a driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-AK12	MARCH	2003~2006	562
DBA-AK12			6,210
UA-BK12			125
UA-BNK12			127
DBA-BNK12			486
DBA-YK12			3,297
UA-BZ11	CUBE		1,138
DBA-BZ11			2,035
UA-BNZ11			153
DBA-BNZ11			607
DBA-YZ11			3,388
UA-BGZ11			576
DBA-BGZ11			375
DBA-YGZ11			1,304
DBA-YGNZ11	265		
		TOTAL	20,648