VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2689	DATE	December 27, 2010	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Automatic transmission fluid may be leaked out from the plug on propeller shaft assembly, which supplied as spare parts and installed on the vehicles mentioned below, as the caulking process applied on the propeller shaft for the plug at manufacturing process was found not enough.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GD-DA52V	Every	2000	1
LE-DA62V	Every	2003~2004	3
GD-DG52V	Scrum	2001	1
		TOTAL	5