

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

 Domestic/~~Import~~ Vehicles

| CAMPAIGN No. | 2688 | DATE | January 14 . 2011 | |
|-----------------------|---|---------------------|-------------------|----|
| MANUFACTURER | Komatsu Utility Co. , Ltd. | | | |
| DESCRIPTION OF DEFECT | Due to improper brake piping, a certain pipe might interfere an optional control valve. Therefore if a machine is continuously used under the above condition, the pipe might get cracked because of vibration during driving, and in the worst case, the brake might not work by brake oil leaking. | | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | |
| SM225 | — | 2005~2008 | 7 | |
| SM226 | FG30 | 2007 | 1 | |
| SB-SM228 | — | 2005~2009 | 23 | |
| SB-SM229 | — | 2006~2009 | 8 | |
| SB-M235 | — | 2006~2007 | 2 | |
| EBT-SM225 | FG25 | 2008~2010 | 4 | |
| EBT-SM226 | FG30 | 2010 | 1 | |
| EDM-SM228 | FD20,FD25 | 2009~2010 | 6 | |
| M226 | — | 2006 | 1 | |
| SB-M228 | — | 2006~2009 | 4 | |
| SB-M229 | — | 2005~2009 | 8 | |
| SB-M230 | — | 2005~2007 | 4 | |
| SB-M231 | — | 2005~2009 | 9 | |
| EBT-M226 | FG30 | 2008~2010 | 4 | |
| EDM-M229 | FD30 | 2009~2010 | 3 | |
| KDN-M231 | FD30H | 2009 | 2 | |
| | | | TOTAL | 87 |