

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2695	DATE	Jan.26.2011
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to insufficient tightening of the fuel pressure sensor connected to the engine fuel delivery pipe, there is a possibility that, over time, the pressure sensor could loosen by engine vibration etc. If loosening occurs, fuel could leak through the threaded portion of the sensor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRS180	CROWN	2007-2008	8,638
DBA-GRS181		2007-2008	1,000
DBA-GRS200		2008	23,639
DBA-GRS201		2008-2009	2,338
DBA-GRX120	MARK X	2007-2009	25,554
DBA-GRX125		2007-2009	2,873
DBA-GSE20	IS250	2007-2009	5,871
		2007-2009	3,832

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GSE25	IS250	2007-2009	544
		2007-2009	301
		TOTAL	74,590