

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	2696	DATE	January 28, 2011
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	There is a potential that some internal element of the machine controller (MCU) could be damaged by the static electricity built on the vehicle chassis. This is because the static electricity may pass into the brake light circuit due to the poor protection circuit for the brake light driver within the MCU. If this condition persists, the brake light may be kept turned on, or the engine may not restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-65J4	65ZV-2	2008-2010	83
EDR-RM06	LK190Z-6	2008-2010	3
JDS-6DC1	65DV-2	2007-2010	8
JDS-70C5	70ZV-2	2007-2010	118
JDS-RE07	LK230Z-6	2007-2010	10
JDS-80C5	80ZV-2	2007-2010	70
JDS-RF06	LK270Z-6	2007-2009	3
JDS-85C5	85ZV-2	2007-2010	29
JDS-RJ06	LK310Z-6	2007	1
JDS-90C5	90ZV-2	2007-2010	13
JDS-97C5	97ZV-2	2007-2010	4
TOTAL			342