

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2706	DATE	February 17 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Due to an inadequate connection of the acceleration control wiring, contact resistance can occur in the jointed portion. Thus, there is a possibility that the acceleration sensor output voltage may increase, thereby causing a rise in engine revolution.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KH-UBS73DW	BIGHORN	1998-2001	272
KH-UBS73GW		1998-2002	9,176
KH-UBS73GWH	HORIZON	1998-1999	66
TOTAL			9,514