

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	Gai-1733	DATE	February 17 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Due to an inadequate connection of the acceleration control wiring, contact resistance can occur in the jointed portion. Thus, there is a possibility that the acceleration sensor output voltage may increase, thereby causing a rise in engine revolution.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KH-UES73EW	MU	1998-2001	734
KH-UES73FW	WIZARD	1998-2001	6,939
TOTAL			7,673