

VEHICLE SAFETY / POLLUTION CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No . | 2707 | DATE | 21 / FEB /2011 |
| MANUFACTURER | HITACHI CONSTRUCTION MACHINERY CO., LTD (JAPAN) | | |
| DESCRIPTION OF DEFECT | Because of the improper mounting of the switches which are for detecting neutral and backward positions at the travel lever, there comes excess vertical force from the cam and the switches will be damaged. Therefore the engine might not be started or the backlight might not be lit even when the travel lever is on the backward position. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------|-----------------|---------------------|-------------------|
| - | CC135C-3 | 2006 ~ 2007 | 58 |
| - | HW30VWH | 2006 ~ 2007 | |
| - | CC150C-3 | 2006 ~ 2007 | 56 |
| - | HW41VWH | 2006 ~ 2007 | |
| - | CC135C-3A | 2007 ~ 2009 | 194 |
| - | HW30VWH-2 | 2007 ~ 2009 | |
| - | CC150C-3A | 2007 ~ 2009 | 227 |
| - | HW41VWH-2 | 2007 ~ 2008 | |
| - | CC135-3 | 2006 ~ 2007 | 4 |
| - | CC150-3 | 2006 | 2 |
| - | HW41VSH | 2006 | |
| - | CC135-3A | 2007 ~ 2008 | 6 |
| - | CC150-3A | 2007 ~ 2008 | 6 |
| - | HW41VSH-2 | 2007 | |
| | | TOTAL | 553 |

1. The above model No. may include the machine which is not be applied for this campaign.
2. With regard to *, an alphabetical letter is added for production control.