

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2713	DATE	February 22. 2011
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	Due to improper location of brake switch and brake pedal link, brake swich may not be operated. Therefore if a machine is continuously used under the above condition, brake light might not turn on .		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SC-M217	-	2004～2005	2
SC-M217T	-	2006	1
SC-M218	-	2005	1
SC-M218T	-	2006～2007	3
EDR-M246	FD100,FD115,FD120	2008～2010	10
	FD100	2009	1
EDR-M247	FD135,FD150E,FD160E	2008～2010	15
	FD135,FD150E,FD160E	2008～2009	9
		TOTAL	42