

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2716	DATE	March. 3. 2011
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The characteristics inspection method employed for hybrid system DC-DC converter diodes was inadequate and thereby some diodes may have been damaged during inspection. In the event of continued use with damaged diode, the low-voltage circuit could be short-circuited and the main fuse could be blown, causing the engine to stall and disabling it from restarting.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-FD3	CIVIC HYBRID	2005~2006	7,219
		2006	1,406
		TOTAL	8,625