

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2720	DATE	March 8, 2011
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>As accelerator cable was found improperly installed by a worker, the cable may be damaged if it is continuously used as it is.</p> <p>In the worst case, engine RPM may not be returned to idle even accelerator pedal turned off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-DA64V	EVERY	2010	9
ABA-DA64W			5
		TOTAL	14