

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 7 2 4	DATE	March 9, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	There is a possibility of welding crack due to insufficient welding penetration between the hinge and side plate in the rear frame. If the machine continues to be used under this circumstance, in the worst case, there is a risk of brake malfunction by destruction of the rear frame.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-WA054	WA100M-3	2006	3
		TOTAL	3