

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2736	DATE	March 31 ,2011
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		The supports for installing the fuel tank lack strength. They may be cracked by vibration while the vehicle is moving. Continued use could lead to the advancement of cracks, and at worst, the fule tank could drop off the vehicle.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PKG-FSR90S2	FORWARD	2008	2
		TOTAL	2