

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2739	DATE	Apr.19 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some vehicles, the shape of the body side mounting fixture for the lower radius rod that secures the rear front axle is improper. Water may enter the fixture, causing corrosion. If the vehicle continues to be used in this condition, the mounting fixture may come off in the worst case, impairing driving stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MU612TX	FUSO AERO KING	2000~2003	85
TOTAL			85