

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2741	DATE	Apr.26 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks, the welding of the transmission output shaft is improper. If the vehicle continues to be used in this condition, the welded part of the shaft may break. In the worst case, the vehicle will become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-FP54JDR	FUSO	2006~2007	17
PJ-FP54JER		2006~2006	11
BKG-FP50JDR		2007~2008	10
BKG-FP54JDR		2007~2009	252
BKG-FP54JER		2007~2009	89
BKG-FP54JGR		2007~2008	3
BKG-FP55JDR		2007~2008	14
		TOTAL	396