

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2742	DATE	Apr-28-2011	
MANUFACTURER	PABCO CO.,LTD			
DESCRIPTION OF DEFECT	There is something into which the blinking frequency of the operating state display device of the driver's seat doesn't change in the vehicle where supplementary wipers were installed in the body side when wipers do not function normally because there was no installation of an additional relay for the wipers increase.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
CBF-SQ2F24	ATLAS	2008~2010	78	
PDG-SZ2F24		2008~2010	107	
PDG-SZ5F24		2010	1	
		TOTAL	186	

|

|