

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2749	DATE	May.26.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trucks and trailer tractors equipped with the 12speed automated manual transmission, due to improper machining of the cylinder on the shift unit and poor greasing onto the shaft, the shaft can be interrupted to rotate smoothly causing the shift position sensor connected to the shaft fail to sense the shift position, and the sift unit to shift gear resulting in a vehicle stop in the road if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FN1EYBG	Hino Profia	2010	1
LKG-FQ1EWBG LKG-FQ1EWBJ		2010	9
LKG-FR1EXBA LKG-FR1EXBG LKG-FR1EXBJ		2010	90
LKG-FR1EZBG LKG-FR1EZBJ		2010	25
LKG-FS1EWBA LKG-FS1EWBG		2010	5
LKG-FS1EZBA LKG-FS1EZBG		2010	3
LKG-FW1EBBJ		2010	1
LKG-FW1EWBA		2010	2
LKG-FW1EXBG LKG-FW1EXBJ		2010	127
LKG-FW1EYBG		2010	3
LKG-FW1EZBG LKG-FW1EZBJ		2010	18
LKG-SH1EDAG LKG-SH1EDAJ		2010	51
LKG-SH1EEAG		2010	1
		TOTAL	336