

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	2756	DATE	May 27, 2011
MANUFACTURER	KCM Corporation.		
DESCRIPTION OF DEFECT	<p>In the steering system, there was a potential that the steering shaft fixing bolts might be loosened due to insufficient tightening torque of these bolts.</p> <p>When this condition continues, the steering shaft and the steering valve shaft would be separated, and the steering wheel becomes inoperative.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-65J4	65ZV-2	2007-2011	142
EDR-RM06	LK190Z-6		6
EDR-A4SDT50	4SDT50		4
JDS-6DC1	65DV-2		9
JDS-70C5	70ZV-2		171
JDS-RE07	LK230-6		10
			TOTAL