

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2755	DATE	May. 31 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	If the inside of injectors are abnormally worn due to reasons such as usage of poor quality fuel, the fuel injection quantity may increase and cause cracks in the pistons. Combustion gas leaking through these cracks will in turn cause increase in the pressure inside the crankcase. If this happens, engine oil may spout out from the rocker cover. In the worst case, a fire could result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FK61FG	FUSO FIGHTER	1999~2004	2
KK-FK61FGY		1999~2001	22
KK-FK61FH		1999~2004	160
KK-FK61FHY		1999~2002	37
KK-FK61FJ		1998~2004	192
KK-FK61FJY		1999~2001	33
KK-FK61FK		1999~2004	432
KK-FK61FKY		1998~2002	106
KK-FK61FL		1999~2004	90
KK-FK61FLY		1999~2002	56
KK-FK61FM		1999~2004	99
KK-FK61FMY		1999~2002	70
KK-FK61FS		1999~2004	51
KL-FK61FGZ		1999~2004	57
KL-FK61FHZ		1999~2004	76
KL-FK61FJZ		1999~2004	141
KL-FK61FKZ		1998~2004	343
KL-FK61FLZ		1999~2004	218
KL-FK61FMZ		1999~2004	201
KL-FK61FSY		1999~2002	26
KL-FK61FSZ		1999~2004	56
KL-FK64FHZ		2002~2004	10
KL-FK64FJZ		2003~2004	6
KL-FK64FKZ		2002~2004	52
KL-FK64FLZ		2002~2004	85
KL-FK64FMZ		2002~2004	107
KL-FM62FHZ		1999~2004	38
KL-FM62FJZ		1999~2004	80
KL-FM62FLZ		1999~2004	242
KL-FM62FMZ		1999~2004	220
KL-FM62FSZ		1999~2004	86
KL-FN61FK		1999~2001	23
KL-FN61FL		1999~2002	43
KL-FN61FM	1999~2002	43	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-FQ61FJ	FUSO FIGHTER	2000~2003	83
KL-FQ61FK		1999~2004	237
KL-FQ61FM		1999~2004	210
KL-FQ61FN		1999~2004	256
KL-FQ61FS		1999~2004	95
KL-FQ61FU		1999~2004	192
KK-MK25FJ	FUSO AERO MIDI	1999~2004	113
KK-MK26FJ		1999~2004	87
KK-MM85FH	FUSO AERO BUS	1999~2004	85
KK-MM86FH		1999~2004	590
		TOTAL	5,451