

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2752	DATE	Jun.1.2011
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the brake tube on the subject vehicles between brake master cylinder and the brake actuator, due to an inadequate cleaning of the inside of the brake tube during the manufacturing process, there is a possibility that foreign material can be found inside the brake tube. Potentially, the foreign material can move into the brake master cylinder and be caught in the seal of the brake master cylinder. If this occurs, pedal travel can increase which causes a decrease of brake force.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KGJ10	iQ	2008-2010	18,213
DBA-NGJ10 DBA-NGJ10 "kai"(modified)		2009-2010	3,423
		TOTAL	21,636