

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	2760	DATE	June-14-2011
MANUFACTURER	Yano Special Vehicle Manufacturing Co, Ltd		
DESCRIPTION OF DEFECT	In the axle of an in-vehicle trailer, there is something where strength is insufficient because the cylinder installation boss's for axle expansion and contraction welding is improper. Therefore, the crack is caused by the vibration etc. when running in the boss weld if it keeps using it under such a condition, and, in the worst case, the axle might be fractured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ARSTC010		2003～2004	3
ARSTC016		2004～2005	17
ARSTC018		2004,2004	2
ARSTC019		2004～2005	4
ARSTC020		2004～2005	3
ARSTC021		2004	1
ARSTC021A		2007	1
ARSTC022		2004,2004	2
ARSTC023		2004,2004	2
ARSTC024		2004	1
ARSTC025		2004	1
ARSTC026		2004	3
ARSTC027		2004～2004	10
ARSTC028		2004,2004	2
ARSTC029		2004～2005	3
ARSTC030		2004,2005	2
ARSTC031		2005,2005	2
ARSTC032		2005	1

ARSTC033		2005	1
ARSTC034		2005,2005	2
ARSTC035		2005～2005	6
ARSTC035A		2006～2007	12
ARSTC036		2005～2005	3
ARSTC037		2005～2007	6
ARSTC038		2005	1
ARSTC039		2005～2006	17
ARSTC040		2005	1
ARSTC041	-	2005～2005	4
ARSTC041A		2006～2007	10
ARSTC046		2005	1
ARSTC046A		2007	1
ARSTC049		2006,2006	2
ARSTC050		2006～2007	4
ARSTC050A		2008	1
ARSTC051		2006,2006	2
ARSTC057A		2006	1
ARSTC059		2006	1
ARSTC062		2006～2007	7
ARSTC063		2006	1
ARSTC068		2006	1
ARSTC069		2007	1
ARSTC072		2007,2007	2
ARSTC073		2007,2007	2
ARSTC075		2007	1
ARSTC082A		2008	1
		TOTAL	152