

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2767	DATE	June 14. 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to improper structure of rubber mounts which are tightened to steering column bracket of the frame, if overload is applied to the steering column, the rubber mounts might be broken. Therefore if a machine is continuously used under such condition, the steering column might become unstable and in the worst case, an operator can not control steering.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M187	-	2001~2004	23
SB-M187		2004~2006	28
SB-M187T		2006~2010	53
		TOTAL	104