

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2773	DATE	June 21 ,2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Because a bracket mounting an air tank, etc. on a heavy-duty truck is not strong enough, the vibration of a vehicle body, etc. may cause this bracket to crack. If the vehicle continues to be operated under this condition, the air tank may be detached and fall in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CVR52A	GIGA	2010	1
LKG-CVR77A		2010-2011	31
LKG-CXG77AT		2010	1
LKG-CXM77A		2010-2011	2
LKG-CXM77AT		2010-2011	3
LKG-CXY77AJ		2010-2011	20
LKG-CYE77AM		2010-2011	21
LKG-CYG77AM		2010-2011	85
LKG-CYH77A		2010-2011	19
LKG-CYJ77A		2010-2011	1,458
LKG-CYJ77AA			
LKG-CYJ77AL		2010-2011	14
LKG-CYJ77AZ		2010-2011	12
LKG-CYL77A		2010-2011	894
LKG-CYL77AA			
LKG-CYL77AM		2010-2011	62
LKG-CYL77AZ		2010-2011	22
LDG-CYM52AM		2010	1
LKG-CYM77A		2010-2011	59
LKG-CYM77AM		2010-2011	31
LKG-CYM77AZ		2010-2011	4
LKG-CYY77A		2010-2011	54

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYY77AJ	GIGA	2010-2011	14
LKG-CYY77AY		2010-2011	124
LKG-CYY77AZ		2010-2011	2
LKG-CYZ77A		2010-2011	77
LKG-CYZ77AJ		2010-2011	13
LKG-CYZ77AM		2010-2011	60
LDG-CYZ77AMQ		2010-2011	13
LDG-CYZ77AV		2010-2011	3
		TOTAL	3,100