

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2777	DATE	Jun. 28, 2011
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	<p>In the power transmission device of the Crop-dusting Vehicle, the Clutch Disk might be damaged because the power of the engine is not well buffered by the Torsion Spring of the Clutch Disk that comes from improper installation of the Pressure Plate, which is transmitting the power of the engine.</p> <p>Therefore, the Crop-dusting Vehicle might become impossible to run because the power of the engine cannot be transmitted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
H3	3S-HE640HC	2011-2011	8
	SSA-Z600T	2011-2011	12
H4	3S-H630	2011-2011	7
	SSA-Z600	2011-2011	13
TOTAL			40