

## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

### Domestic Vehicles

<b>CAMPAIGN No.</b>	2 7 7 2	<b>DATE</b>	June 30, 2011
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	As the reinforced structure of the exhaust tail pipe is improper, the reinforcement plate of the pipe may develop a crack during its use. In the worst case, the pipe may break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-EC22S	TWIN	2003~2004	7,029
CBA-EC22S		2004~2005	3,016
ZA-EC22S		2004	3
CAA-EC22S		2004~2005	16
		<b>TOTAL</b>	<b>10,064</b>