

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2781	DATE	July 1,2011
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>IN THE 4-SPEED AUTOMATIC TRANSMISSION OF THE SUBJECT VEHICLES, SINCE THE LUBRICATING OIL ROUTE IN THE TRANSMISSION CASE IS INAPPROPRIATE, THE LUBRICATION FOR THE PROPELLER SHAFT MAY BECOME INSUFFICIENT AT HIGH SPEED DRIVING (HIGHER THAN 65KM/H). IF THE VEHICLE IS CONTINUOUSLY OPERATED IN THIS CONDITION, THE REAR PORTION OF THE TRANSMISSION COULD BE BROKEN RESULTING IN THE VEHICLE UNABLE TO BE DRIVEN. IN SOME MODELS, THE PROPELLER SHAFT COULD BE DETACHED CAUSING THE FUEL TANK TO BE DAMAGED, WHICH COULD RESULT IN THE FUEL LEAKAGE.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LE-U71V	CLIPPER	VEHICLES IN WHICH THE SUBJECT SERVICE PART IS INSTALLED	4
GBD-U71V			98
CBA-U71W	CLIPPER RIO		28
		TOTAL	130