

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2778	DATE	Jul. 7 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Due to the wrong data written to the engine ECU, the vehicle may fail to comply with the requirements of the exhaust gas regulations. Additionally, on buses, the cooling fan may not operate leading to an overheat. On trucks, the engine control lamp may turn on falsely.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FS54VZ	FUSO	2010~2010	2
LKG-FU50VY		2010	1
LKG-FU54VZ		2010~2010	4
LKG-FU55VZ		2010	1
LKG-FV50VZ		2010	1
LKG-MS96VP		FUSO AERO ACE	2010~2011
		TOTAL	12