VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 2 7 8 2
 DATE
 July.12.2011

 MANUFACTURER
 UD Trucks Corporation
 July.12.2011

 DESCRIPTION OF DEFECT
 Since the length of fitting rubber located at the bottom part of fuel tank is inappropriate, and due to the vibration during the vehicle is in motion, cracks to occur at the bottom part of the fuel tank. Thus, if the fuel tank to be used as it is continuously with the above mentioned condition, it may result in the fuel leakage from the cracks.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RA273KAN PDG-RA273KAN	_	2005~2010	212
ADG-RA273MAN PDG-RA273MAN	_	2005~2010	103
ADG-RA273PAN	_	2005~2006	7
PKG-RA274KAN	_	2006~2010	534
PKG-RA274MAN	_	2006~2010	121
PKG-RA274PAN	_	2006~2009	54
PDG-AA273KAN	_	2008~2009	46
PDG-AA273MAN	_	2007~2008	57
PKG-AA274KAN	_	2007~2010	149
PKG-AA274MAN	_	2007~2009	50
PKG-AA274PAN	_	2007~2010	38
		TOTAL	1,371