

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2787	DATE	Jul.26.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium duty trucks, due to the designed strength of the welding of pipe and spline shaft on the propeller shaft assembly is insufficient, the welding may have micro cracks during the process for the correction of straightness of the propeller shaft assembly. The cracks may grow up during the vehicle operation, and possibly cause the propeller shaft to be broken if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FC5JDEA	Hino Ranger	2002～2004	15
PB-FC7JCFA		2004～2005	28
PB-FC7JDFA		2004～2005	170
ADG-FC7JCWA BDG-FC7JCWA		2005～2009	68
ADG-FC7JDWA BDG-FC7JDWA		2005～2010	561
PB-FD7JDFA		2004～2005	235
PB-FD7JEFA		2004～2005	115
ADG-FD7JDWA BDG-FD7JDWA		2005～2010	661
ADG-FD7JEW BDG-FD7JEW		2005～2010	437
BKG-FD7JDYA		2007～2010	188
KS-FE7JEFA PK-FE7JEFA		2004～2005	65
ADG-FE7JEW BDG-FE7JEW		2005～2010	321
LDG-FE7JEAA		2010	16
KS-FJ7JDFA PK-FJ7JDFA		2004～2005	137
ADG-FJ7JDWA BDG-FJ7JDWA		2005～2010	575
LDG-FJ7JDAA		2010	12
PB-GC7JDFA		2004～2005	21
ADG-GC7JDWA BDG-GC7JDWA		2005～2010	130
BKG-GC7JDYA		2008～2010	47
PB-GD7JEFA		2004～2005	8
ADG-GD7JEW BDG-GD7JEW ADG-GD7JEWAKAI		2005～2009	61
BKG-GD7JEYA		2008～2010	44
PB-GD7JGFAKAI		2004	3
ADG-GD7JGWAKAI BDG-GD7JGWAKAI		2006～2007	4
		TOTAL	3,922