

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1771	DATE	July 28, 2011
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to low durability of side impact sensor wiring at both RH and LH front door wire harness, fatigue breakage might cause electric failure. If the vehicle is driven further, air bag warning lamp be "ON" and in the worst case, side air bag will not work at side collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JC27	Dodge JC	2009	118
—	Dodge JC	2009	1
		Total	119