

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2794	DATE	August 11, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	On an angle sensor of the accelerator pedal, because of improper structure of inner parts, accelerator pedal might not output fitting level signal according to pedal angle, or idling position switch might output idling position signal continuously. Therefore a vehicle might not gain speed according to pedal angle, or might not travel.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M190	-	2002 ~ 2005	642
ZAF-M190T	-	2005 ~ 2006	178
M193	-	2003 ~ 2005	85
ZAF-M193T	-	2005 ~ 2010	174
ZAF-SM236	FB09H,FB10,FB14,FB15,FB15HB	2006 ~ 2011	933
ZAF-SM236K	FB09H,FB10,FB14,FB15,FB15HB	2011	19
ZAF-SM237	FB18,FB18HB,FB20A,FB20AHB	2007 ~ 2011	214
ZAF-SM237K	FB18,FB20A,FB20AHB	2011	4
ZAF-M238	FB09ML,FB10ML,FB13ML	2006 ~ 2011	51
ZAF-M239	FB15ML	2007 ~ 2011	81
ZAF-M239K	FB15ML	2011	2
ZAF-SM243	FB15G,FB18G,FB20AG	2007 ~ 2010	9
ZAF-M254	FB25HB	2008 ~ 2011	17
M191	-	2004	1
M194	-	2004 ~ 2005	4
ZAF-M194T	-	2006 ~ 2010	3
M195	-	2004	1
ZAF-M195T	-	2007 ~ 2008	3
ZAF-M237	FB20A	2007	1
		TOTAL	2,422