

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 7 9 8	DATE	August 25. 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	There is a risk of cracking at bottom of a license-plate light cover due to lack of strength. If the machine continues to be used under this circumstance, a part of cover may break and cover may drop off then white light shall be visible from behind of a vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD-GD020A	GD755-3 GH320-3	2006~2008	61
JDS-GD024	GD755-5 GH320-5	2008~2011	82
SC-GD013A	GD655-3	2005~2008	59
JDS-GD022	GD655-3	2008~2011	97
		TOTAL	299