VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

Domestic venicles					
CAMPAIGN No.	2803	DATE	E Ser	b. 1	2011
MANUFACTURER	MORITA-ECONOS CORPORATION				
DESCRIPTION OF DEFECT	Some of the fuel hoses of the dump truck are contact with the toolbox due to the improper fixation upon installation of the toolbox. Accordingly, there is a risk of fire caused by the fuel leakage, in the worst case, if the fuel hose is damaged due to the vibration, etc. while the dump truck is running.				
TYPE	COMMERCI NAME	AL	MODEL YEAR RECALLED		JMBER OF VEHICLE
BKG-NKR85AN	- ISUZU EL	E 2008	$2008 \sim 2011$		30
BKG-NMR85AN		ι1 ⁻ ι	2000 - 2011		5

X Vehicle number and production period indicated in a list may includes vehicles which do not have any defect.

TOTAL

35