

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2 8 0 8	DATE	September , 7 , 2011
MANUFACTURER	SOHSHIN CO., LTD.		
DESCRIPTION OF DEFECT	Because the shape of a support bracket fixing a fuel tank is inappropriate, in a fuel tank, a crack may occur by the vibration of the body in the lower part of the fuel tank. Therefore a crack progresses when I continue just using it, and fuel might leak from the crack department concerned when I am the worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PY5KUFM	—	2000~2010	24
		TOTAL	24