

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2809	DATE	September 7, 2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the commonrail type fuel injection systems for the route buses, it has been found that some commonrails had low the strength due to poor materials and processing. There is a possibility that the commonrails are cracked by repeated pressure fluctuations in time of fuel supply, thereby causing fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	ERGA	2004-2007	1,199
PDG-LV234L2 PKG-LV234L2		2007-2010	1,111
LDG-LV234L3 LKG-LV234L3		2010	17
PJ-LV234N1		2004-2007	633
PDG-LV234N2 PKG-LV234N2		2007-2010	687
LKG-LV234N3		2010	35
PJ-LV234Q1		2005-2007	103
PDG-LV234Q2 PKG-LV234Q2		2007-2010	167
LKG-LV234Q3		2010	3
PA-LR234J1		ERGA MIO	2004-2007
PDG-LR234J2	2007-2011		1,134
PA-KR234J1	HINO RAINBOW II	2004-2007	253
		TOTAL	6,041

