

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2810	DATE	Sep.7.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the commonrail type fuel injection systems for the route buses, it has been found that some commonrails had low the strength due to poor materials and processing. There is a possibility that the commonrails are cracked by repeated pressure fluctuations in time of fuel supply, thereby causing fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	Hino Blue Ribbon II	2004~2007	591
PJ-KV234N1		2005~2007	543
PJ-KV234Q1		2005~2007	213
PJ-KV234Q1KAI			
PDG-KV234L2		2007~2010	529
PKG-KV234L2			
PDG-KV234L2KAI			
PDG-KV234N2		2007~2010	653
PKG-KV234N2			
PDG-KV234N2KAI			
PKG-KV234N2KAI			
PDG-KV234Q2		2007~2010	226
PKG-KV234Q2			
PDG-KV234Q2KAI			
PKG-KV234Q2KAI			
LDG-KV234L3		2010	2
LKG-KV234L3			
LKG-KV234N3		2010	20
LKG-KV234N3KAI			
LKG-KV234Q3	2010	3	
PDG-KR234J2	Hino Rainbow II	2007~2010	739
PDG-KR234J2KAI			
		TOTAL	3,519