

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2811	DATE	September 7, 2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the route buses equipped with the headlight left-on reminder, it has been found that the electric circuit of the reminder was inadequately arranged, so that current bigger than expected might flow in the headlight switch, causing the switch contact to wear out. If the affected buses are used as they are, there is a possibility that the switch contact is broken and the headlights malfunction.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-LT233J2	ERGA	2003	4
PJ-LV234L1		2005-2007	138
PKG-LV234L2		2007-2010	89
PJ-LV234N1		2006-2007	3
KL-LV280L1		2004	13
KL-LV280N1		2004	1
KL-LV834L1		2005	2
PDG-LR234J2	ERGA MIO	2008-2010	15
		TOTAL	265

