## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2807	DATE	Sep. 14, 2011
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Relevant coil is occasionally disconnected while using because coil-winding procedure is inappropriate in the manufacture process of engine crank angle sensor.  Therefore engine may stop while driving or engine may not start up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-L235S	ESSE	2006-2007	11,027
CBA-L245S			1,827
CBA-L405S	SONICA		3,407
CBA-L415S			391
CBA-L175S	MOVE		49,467
DBA-L175S			
CBA-L185S			9,860
DBA-L185S			
CBA-L275S			21,364
DBA-L275S	MIRA		
CBA-L285S			3,710
DBA-L285S			
		TOTAL	101,053